

Autonics PULSE METER MP5M SERIES INSTRUCTION MANUAL



Thank you for choosing our Autonics product. Please read the following safety considerations before use.

Safety Considerations

- Please observe all safety considerations for safe and proper product operation to avoid hazards.
- Safety considerations are categorized as follows:
 - Warning:** Failure to follow these instructions may result in serious injury or death.
 - Caution:** Failure to follow these instructions may result in personal injury or product damage.
- The symbols used on the product and instruction manual represent the following:
 - ⚠ symbol represents caution due to special circumstances in which hazards may occur.

Warning

- Fail-safe device must be installed when using the unit with machinery that may cause serious injury or substantial economic loss. (e.g. nuclear power control, medical equipment, ships, vehicles, railways, aircraft, combustion apparatus, safety equipment, crime/disaster prevention devices, etc.) Failure to follow this instruction may result in personal injury, fire, or economic loss.
- The unit must be installed on a device panel before use. Failure to follow this instruction may result in electric shock.
- Do not connect, repair, or inspect the unit while connected to a power source. Failure to follow this instruction may result in electric shock.
- Do not disassemble or modify the unit. Please contact us if necessary. Failure to follow this instruction may result in electric shock or fire.
- Check the terminal numbers before connecting the power source and measurement input. Failure to follow this instruction may result in fire.

Caution

- Do not use the unit outdoors. Failure to follow this instruction may result in electric shock or shortening the life cycle of the unit.
- When connecting the power input or measuring input, make sure to tighten the terminal screw bolt above 0.74N·m to 0.90N·m. Contact failure may result in fire.
- Use the unit within the rated specifications. Failure to follow this instruction may result in electric shock or shortening the life cycle of the unit.
- Do not use loads beyond the rated switching capacity of the relay contact. Failure to follow this instruction may result in insulation failure, contact failure, contact bonding, damage, or fire.
- Do not use water or oil-based detergent when cleaning the unit. Use dry cloth to clean the unit. Failure to follow these instructions may result in electric shock or fire.
- Do not use the unit where flammable or explosive gas, humidity, direct sunlight, radiant heat, vibration, and impact may be present. Failure to follow this instruction may result in fire or explosion.
- Keep dust and wire residue from flowing into the unit. Failure to follow this instruction may result in fire or product malfunction.
- Check the polarity of the measurement input contact before wiring the unit. Failure to follow this instruction may result in fire or explosion.

Ordering Information

MP 5 M - 4 N	Main output (Comparative value output)	15
N	Indicator	16
1	Relay single (high-limit) output+ NPN open collector output	17
2	Relay dual (high/low-limit) output+ NPN open collector output	
2	24VAC 50/60Hz, 24-48VDC	
4	100-240VAC 50/60Hz	
M	DIN W72×H72mm	
5	99999 (5 Digit)	
MP	PULSE METER	

Product Description

- Display:** Displays current value in RUN mode. Alternately displays setting parameters and corresponding value in SETTING mode.
- MODE key:** In RUN mode, press the key once to check max./min. value. In RUN mode, hold the key for over 2 sec. to enter parameter groups.
- Navigation keys:** Select parameter groups, and select or setting values in the corresponding parameters.
- Output status indicator:**
- Thumbwheel switch for HIGH/LOW setting value:**

※The high-limit setting model(MP5M-□1) does not include the dotted line parts.
 ※The above specifications are subject to change and some models may be discontinued without notice.


Specifications

Model	MP5M-2N	MP5M-4N	MP5M-21	MP5M-41	MP5M-22	MP5M-42
Indicator			High-limit setting		High/Low-limit setting	
Display method	7 Segment LED (zero blanking method)					
Character size	W4×H8mm					
Display range	0.0001 to 99999					
Power supply	AC voltage	100-240VAC 50/60Hz				
	AC/DC voltage	24VAC 50/60Hz, 24-48VDC				
Power consumption	AC voltage	Max. 9.0VA (100-240VAC 50/60Hz)				
	AC/DC voltage	Max. 6.5VA (24VAC 50/60Hz), Max. 5.0W (24-48VDC)				
Permissible voltage range	90 to 110% of rated voltage					
Power for external sensor	12VDC±10%, 80mA					
Input frequency	Solid state input: Max. 50kHz (pulse width: Min. 10µs) Contact input: Max. 45Hz (pulse width: Min. 11ms)					
Input method	[Voltage Input method] High: 4.5-24VDC, Low: 0-1.0VDC, input impedance: 2.4kΩ [No-voltage Input method] Short-circuit impedance: Max. 80Ω, Residual voltage: Max. 1V, Open-circuit impedance: Min. 100kΩ					
Measurement range	Mode F1, F2, F7, F8	: 0.0005Hz to 50kHz				
	Mode F3, F4, F5, F6	: 0.01 to Max. of each time range				
	Mode F9, F10, F11, F14	: 0 to 99999				
	Mode F12, F13	: -19999 to 99999				
Measurement accuracy(23±5°C)	Mode F1, F2, F7, F8: F.S.±0.05% rdg±1 Digit					
	Mode F3, F4, F5, F6: F.S.±0.01% rdg±1 Digit					
Display cycle	OFF(for F2, F14 mode), 0.05, 0.5, 1, 2, 4, 8 sec.(same as update output cycle)					
Operation mode	Frequency/Revolutions/Speed (F1), Passing speed (F2), Cycle (F3), Passing time (F4), Time interval (F5), Time differential (F6), Absolute ratio (F7), Density (F8), Length measurement 1 (F9), Interval (F10), Accumulation (F11), Addition/Subtraction-individual input (F12), Addition/Subtraction-phase difference input (F13), Length measurement 2 (F14)					
Prescale function	Direct input method (0.0001×10 ⁰ to 9.9999×10 ⁹)					
Hysteresis	Direct	0 to 9999 ^{※1}				
Main output	Relay single	250VAC 3A resistive load 1c				—
	Relay dual	—				250VAC 3A resistive load 1a
	NPN open collector quintuple	Max. 30VDC 100mA				
Memory retention	Non-volatile memory (number of inputs: Min. 100,000 operations)					
Insulation resistance	Min. 100MΩ (at 500VDC megger)					
Dielectric strength	2,000VAC 60Hz for 1 min.					
Noise resistance	Square-wave noise by noise simulator (pulse width 1µs) ±2kV					
Vibration	Mechanical	0.75mm amplitude at frequency of 10 to 55Hz in each X, Y, Z direction for 1 hours				
	Malfunction	0.5mm amplitude at frequency of 10 to 55Hz in each X, Y, Z direction for 10 minutes				
Shock	Mechanical	300m/s ² (approx. 30G) in each X, Y, Z direction for 3 times				
	Malfunction	100m/s ² (approx. 30G) in each X, Y, Z direction for 3 times				
Relay life cycle	Mechanical	—				Min. 10,000,000 operations
	Electrical	—				Min. 100,000 operations (250VAC 3A resistive load)
Environment	Ambient temp.	-10 to 50°C, storage: -20 to 60°C				
	Ambient humi.	35 to 85%RH, storage: 35 to 85%RH				
Approval	CE, c, UL, US					
Weight ^{※2}	Approx. 243g (approx. 168g)	Approx. 256g (approx. 181g)	Approx. 265g (approx. 190g)			

※1: Setting range will vary depending on the decimal point.
 ※2: The weight includes packaging. The weight in parentheses is for unit only.
 ※Environment resistance is rated at no freezing or condensation.


Connections

Indicator(MP5M-□N)




- ※1: Operation mode F1 to F10: Display value HOLD
Operation mode F11 to F14: Display value RESET
- ※2: Model Source
MP5M-21 24VAC 50/60Hz
MP5M-22 24-48VDC
MP5M-2N 100-240VAC
MP5M-41 50/60Hz
MP5M-42


High-limit setting(MP5M-□1)



High/Low-limit setting(MP5M-□2)




Dimensions




※The high-limit setting model(MP5M-□1) does not include the dotted line parts.

Parameter Groups








- Press the **MODE** key to select or set the desired value.
- Press the **MODE** key once after changing the setting value, to save the setting value and move to the next parameter.
- Hold the **MODE** key for 1.5 sec. at any parameters to return to the select parameter group mode.
- Hold the **MODE** key for 3 sec. to save the setting value and return to RUN mode after changing the setting value.
- If there is no key input for 60 sec. while setting the parameters, the new settings are ignored, and the unit will return to RUN mode with previous settings.
- The dotted line parameters may not appear depending on output specifications or other parameter settings. Please refer to "Operation mode by parameter group".
- Each parameter and corresponding setting value will flash alternately every 0.5 sec.

Parameter 0 group



Parameter 1 group



Operation Mode By Parameter Groups

Parameter	F1	F2	F3	F4	F5	F6	F7	F8	F9	F10	F11	F12	F13	F14
0 group	HPEL										X			X
	LPEL										X			X
1 group	In-A													
	In-B													
	out-H													
	out-L													
	HYS													
	GUArd													
	Aut.aR													
	Aut.ab													
	NEo													
2 group	dot													
	tUnit													
	PSC.A													
	PSC.B													
	PSC.y													
	PSC.b.y													
	dI SPt													
	CoUnb													
3 group	LoC													

※1: Only appears in high/low-limit setting models.
 ※2: Only appears in high-limit setting models, high/low-limit setting models.
 ※3: (●) Only nPnHF or PnPnHF setting are available for Input B sensor.
 ※4: The settings for In-b and In-a are applied.
 ※5: (●) F output mode[out-F] cannot be set.
 ※6: (■) setting range: oFF, 005, 05, 1, 2, 4, 8
Monitoring delay function by output mode

Output mode	S mode	H mode	L mode	B mode	I mode	F mode
Parameter	StAr-d	out-h	out-L	out-b	out-I	out-F
Comparative output limit		X	X	X	X	X
Start compensation timer						

Input Specifications


1. Input signal

- Solid state input
 - Input frequency: max. 50kHz (standard duty ratio of input signal: 1:1, ON/OFF pulse width: min. 10μs of each)
 - Input voltage level: ON voltage → 4.5-24V, OFF voltage → 0-1.0V
- Contact input
 - Input frequency: max. 45Hz (when each ON/OFF pulse width is over 11ms)
 - Contact specifications: 12VDC, stable switching of load current as small as 5mA


2. Input type

MP5M allows selection between NPN input (solid state/contact) or PNP input (solid state/contact).

(1) NPN input type



(2) PNP input type



Operation Modes [MODE]

F1 Mode: Frequency/Revolutions/Speed


Measures the frequency of input A and displays the calculated frequency, revolutions, and speed.

- Frequency (Hz) = $f \times \alpha$ ($\alpha = 1[\text{sec}]$)
- Revolutions (rpm) = $f \times \alpha$ ($\alpha = 60[\text{sec}]$)
- Speed (m/min) = $f \times \alpha$ ($\alpha = 60L[\text{sec}]$)

Display value and display unit

Display value	Display unit	α (prescale value)
Frequency	Hz	1
	kHz	0.001
Revolutions	rps	1
	rpm (default)	60
Speed	mm/sec	1,000L
	cm/sec	100L
	m/sec (default)	1L
	m/min	60L
	km/hour	3.6L

Timing chart



F2 Mode: Passing Speed

Displays the passing speed between input A ON and input B ON.

$$\text{Passing speed (V)} = f \times \alpha \quad (\alpha = L[\text{m}])$$

f : reciprocal of time [sec.] between input A (sensor) ON and input B (sensor) ON.


L : distance between input A (sensor) and input B (sensor) [m]

α : prescale value

Display value and display unit

Display value	Display unit	α (prescale value)
Passing speed	mm/sec	1,000L
	cm/sec	100L
	m/sec (default)	1L
	m/min	60L
	km/hour	3.6L

Timing chart



F3 Mode: Cycle


Displays the measured time from Input A ON to the next ON.

$$\text{Cycle (T)} = t \quad \text{※} t: \text{measurement time [sec]}$$

Display value and display unit (Unit of parameter 2)

Display value	Display unit	Min.
Cycle	Sec.	999.99s
	(default)	999.99m
	9999.9s	9999.9m
	99999s	99999m

Timing chart



F4 Mode: Passing Time

Measures the time from Input A ON to the next ON, and displays the passing time of the arbitrary distance.

$$\text{Passing time [sec]} = t \times \alpha$$

$$\alpha = \frac{L[\text{m}]}{\text{Distance advanced in 1 pulse cycle [m]}}$$


t : measured time [sec], L : arbitrary distance [m]

α : prescale value

Display value and display unit (Unit of parameter 2)

Display value	Display unit	Min.
Passing time	SEC	999.99s
	(default)	999.99m
	9999.9s	9999.9m
	99999s	99999m

Timing chart



F5 Mode: Time Interval


Displays measured time of input A ON

$$\text{Time interval (T)} = t \quad \text{※} t: \text{measured time of input A ON [sec]}$$

Display value and display unit (Unit of parameter 2)

Display value	Display unit	Min.
Time interval	Sec.	999.99s
	(default)	999.99m
	9999.9s	9999.9m
	99999s	99999m

Timing chart



F6 Mode: Time Differential

Displays measured time from Input A ON to Input B ON.


$$\text{Time differential (T)} = t(\text{to } t_b)$$

$t(\text{to } t_b)$: measured time from input A ON to input B ON [sec]

Display value and display unit (Unit of parameter 2)

Display value	Display unit	Min.
Time difference	SEC	999.99s
	(default)	999.99m
	9999.9s	9999.9m
	99999s	99999m

Timing chart



F7 Mode: Absolute Ratio

Measures and displays relative speed, amount, speed, etc. of input B against input A in percentage (%).

$$\text{Absolute ratio} = (\text{Input B} / \text{Input A}) \times 100\%$$


$$\text{Absolute ratio} = \frac{\text{Frequency of input B [Hz]} \times \alpha_a}{\text{Frequency of input A [Hz]} \times \alpha_a} \times 100(\%)$$

α_a : Prescale value of input A, α_b : Prescale value of input B

Display value and display unit

Display value	Display unit
Absolute ratio	%

Timing chart



F8 Mode: Density

Measures and displays the density ratio (%) of input B against the total sum of input A and input B.

$$\text{Density} = \frac{\text{Input B}}{\text{Input A} + \text{Input B}} \times 100(\%)$$

$$\text{Density} = \frac{\text{Frequency of Input B [Hz]} \times \alpha_b}{(\text{Frequency of input A [Hz]} \times \alpha_a) + (\text{Frequency of input B [Hz]} \times \alpha_b)} \times 100(\%)$$

α_a : Prescale value of input A, α_b : Prescale value of input B

Display value and display unit

Display value	Display unit
Density	%

Timing chart



F9 Mode: Length Measurement 1

Measure and display the number of input A pulses during input B ON.

$$\text{Length measurement} = P \times \alpha$$

P : Number of input A pulses, α : Prescale value

Display value and display unit

Display value	Display unit
Length measurement	Quantity (default)
	mm
	cm
	m

Timing chart



F10 Mode: Interval

Measures and displays the number of input A pulses from Input B ON to the next ON.

$$\text{Interval} = P \times \alpha$$

P : Number of input A pulses, α : Prescale value

Display value and display unit

Display value	Display unit
Interval	Quantity (default)
	mm
	cm
	m

Timing chart



F11 Mode: Accumulation

Measures and displays the counted value of input A pulses.

$$\text{Accumulation} = P \times \alpha$$

P : Number of input A pulses, α : Prescale value

Operation

① Counts the number of input A pulses.

② Input B is an enable input signal.

During ON, the quantity and display value of input A will be held, and during OFF input A will be re-counted.

③ When RESET input is ON, the integrated counted value will be reset to "0".

F12 Mode: Addition/Subtraction-Individual Input

Displays the counted value from added input A pulses and subtracted input B pulses. When there are two inputs simultaneously, it will not count.


$$\text{Addition/Subtraction} = \text{Input A} \times \alpha - \text{Input B} \times \beta$$

α : Prescale value of input A, β : Prescale value of input B

Display value and display unit

Display value	Display unit
Addition/Subtraction (individual input)	Quantity

Operation and timing chart



F13 Mode: Addition/Subtraction-Phase difference input


When input A is low, counting is added to the low of input B. When input A is high, counting is subtracted from the high of input B.

α : Prescale value of input A, β : Prescale value of input B

Display value and display unit

Display value	Display unit
Addition/Subtraction (phase difference input)	Quantity

Timing chart



F14 Mode: Length Measurement 2

Measures and displays the number of pulses from input A until the value of input B reaches the set value.


$$\text{Length measurement 2} = P \times \alpha \quad (\text{until the setting value of input B})$$

P : Number of input A pulses, α : Prescale value

Display value and display unit

Display value	Display unit
Length measurement 2	Quantity (EA)

Timing chart (e.g.) setting value of Input B=4



Output Modes [OUT-E]

MP5M-1: S output mode, MP5M-2: S, B, H, L, I, F output mode

① Requirement for setting comparative value: (B output mode) $L < H$, (F output mode) $L < H$, (other output modes) individual output operation regardless of size or order of set comparative values.


※1: hysteresis

S(Standard) Output Mode [S-E]



H output : Comparative value $H \leq$ Display value
L output : Comparative value $L \geq$ Display value

I(One Shot) Output Mode [I-E]




H output : Comparative value $H \leq$ Display value
L output : Comparative value $L \leq$ Display value

H(High) Output Mode [H-E]



H output : Comparative value $H \leq$ Display value
L output : Comparative value $L \leq$ Display value

L(Low) Output Mode [L-E]



H output : Comparative value $H \geq$ Display value
L output : Comparative value $L \geq$ Display value

F(Deflection) Output Mode [F-E]

Transmits outputs when the saved setting value exceeds H deviation or L deviation.

① Saving setting value: Press the MODE+ keys to save as setting value.

② Checking setting value: Press the key to check the setting value.

③ Setting deviation: Based on the setting value, set H deviation, L deviation by the thumbwheel switches. (the set deviation value is saved during Power OFF until it is re-set.)

④ Deviation setting range: 0.0001 to 99999 (setting range depends on the decimal point [DEC] setting.)

E.g.) Decimal point [DEC]: "0000.0", Setting range: 0.1 to 9999.9




※2: When selecting initial comparative output limit function, it does not transmit outputs.
※3: The graph is assuming that there is a saved setting value prior to the setting value save point. The actual output position may be different.
※The deviation can be set to "0" but the actual operation will be the same as "1".

Function

Hysteresis [HY]

The output may turn ON/OFF frequently near the comparative setting value. To prevent this, set the hysteresis value with the comparative setting value as reference.



※A: hysteresis value
※The hysteresis value can be set to "0" but the actual operation value will be at "1".

Delay Monitoring [DUR]


After supplying power, the starting current of motors and other inputs may experience changes.

This function allows stable control by limiting all outputs for a certain period until the target measurement unit stabilizes. It may also control L outputs until a specific output is reached.

① Comparative output limit function [DEF]: Only for S(Standard), B(Block), F(Deflection) output mode.

② Limits L output before H output.


1) During S(Standard), B(Block) output mode



※After supplying power, there is no initial L comparative output (function removal).

※Each setting value of H, L is not related to their relative sizes. Hence, H value may be lower or equal to L value.


2) During F(Deflection) output mode



※After supplying power, there is no comparative output of L deviation (function removal).

※H and L deviation are not related to their relative sizes. (H deviation setting value > L deviation setting value, H deviation setting value < L deviation setting value)

Start compensation timer function [SET]



Set monitoring delay time so that there is no output during the delay time.

Auto-Zero Time Setting [AUZ]


When there is no input signal during auto-zero set time, the display value is automatically set to 0(zero).

Please set the auto-zero set time so that it is longer than the interval of the slowest input signal.

If the setting time is too long and there is no input signal, the rate at which the display value falls to 0(zero) decreases, and output response rate may slow down.

Prescale [PSC]

Displays values in required units or specific multiples by counting the number of input pulses, then multiplying the number of pulses or the length of pulses by variables (X*10y).



Number of revolutions (rpm) = $f \times \alpha$
= $f \times 60 \times (1 / N)$
= $f \times 60 \times (1 / 4)$
= $f \times 60 \times 0.25$
= $f \times 15$

※f: The number of input pulses per second [Hz],
α: Prescale value
N: The number of pulses per revolution

① Setting prescale value (α=15)
Set mantissa (X) as 1.5000, and exponent (Y) as 1 for prescale value (α)=15.
The same display value can be obtained with a value set as X=0.1500, and Y=2.

Cautions During Use

1. Please separate the unit wiring from high voltage lines or power lines to prevent inductive noise.

2. Install a power switch or circuit breaker to control the power supply.

3. The power switch or circuit breaker should be installed where it is easily accessible by the user.

4. Do not use the unit in the following environments.

① Environments with high vibration or shock.

② Environments with exposure to direct sunlight.

③ Near machinery which produce strong magnetic force or electric noise.

5. Storing the unit

When storing the unit for an extended period, please avoid direct exposure to sunlight. Ambient temperature should be between -20°C to 60°C and ambient humidity should be between 35% to 85%RH. Store in factory packaging for best results.

6. Input line

Please use a shield wire in environments where noise may occur or instances where long measurement input lines are required.

7. Please maintain distance between the power supply line and measurement input line.

8. This product may be used in the following environments

① Indoors

② Max. altitude: 2,000m

③ Pollution degree 2

④ Installation category II

※Failure to follow these instructions may result in product damage.

Major Products

- Photoelectric Sensors
- Fiber Optic Sensors
- Door Sensors
- Door Side Sensors
- Area Sensors
- Proximity Sensors
- Pressure Sensors
- Rotary Encoders
- Connector/Sockets
- Switching Mode Power Supplies
- Control Switches/Lamps/Buzzers
- I/O Terminal Blocks & Cables
- Stepper Motors/Drivers/Motion Controllers
- Graphic/Logic Panels
- Field Network Devices
- Laser Marking System (Fiber, Co., Nd: YAG)
- Laser Welding/Cutting System
- Temperature Controllers
- Temperature/Humidity Transducers
- SSR/Power Controllers
- Counters
- Timers
- Panel Meters
- Tachometer/Pulse(Rate) Meters
- Display Units
- Sensor Controllers

Autonics Corporation
http://www.autonics.com

Trusted Partner in Industrial Automation

■ HEADQUARTERS:

18, Bongsong-ro 513beon-gil, Haendae-gu, Busan, South Korea, 48002

■ OVERSEAS SALES:

#402-303, Bucheon Techno Park, 655, Pyeongcheon-ro, Wonmi-gu, Bucheon, Gyeonggi-do, South Korea, 14502

TEL: 82-32-610-2730 / FAX: 82-32-329-0728

E-mail: sales@autonics.com

EP-E-04-011A